

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. **297**

/SAC/2026-27

Date: **26/5/26**

BUILDING SAFETY CERTIFICATE

It is certified that the existing building **Golden International School , at Rangwasa, Rau , Dist.Indore (MP)** is having block(s) / Floor (s) as per details below:

Detail of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G + 2					

The building is owned/occupied by **Golden International School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on **25/05/2026** (date of inspection) in the presence of **Manager Mr. Jitendra Chouhan** and that the building/premises is fit for occupancy for running school with effect from **25/05/2026** for a period of **01 years** in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on **25/05/2026** at Indore by Sub Divisional Officer PWD, Indore.



Sub Division Officer

PWD Distt. Sub Division No.1, Indore

**Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE**